


OFFICE OF THE ASSISTANT EXECUTIVE ENGINEER
UDAKA (R&B) SUB – DIVISION, UDALA


BUILDING SAFETY CERTIFICATE


It is to Certified that the existing building of St. Mary's School at Divyasinghapur, Udala, Mayurbhanj Odisha is having 2 (two) Blocks as per detail below.

Detail of Block(s) in School	Block 1	Block-2
No. of Floor(s) in the Block	Three story 3 floors	Double story 2 floors

The building is owned/ occupied by St. Mary's School have complied with the building safety requirements in accordance with National Building Code Rules, and Inspected/ verified by the under signed (Name: Rajendra Kishan, Asst. Executive Engineer, Udala (R&B) Sub-Division on dated 18.02.2025 in the presence Sri Raghunath Karmakar, Manager cum Chairman, St. Mary's School, Udala and that the building / Premises is fit for occupancy for running school with effect for the Academic year 2025-26, 2026-27 & 2027-28 under normal weather condition.


Assistant Executive Engineer,
Udala (R&B) Sub-Division.


Principal
St. Mary's School, Udala
Mayurbhanj


Manager-cum-Chairman
St. Mary's School, Udala